DI12M-14

DTC		Throttle Pedal Position Sensor/Switch "A" Circuit Range/Performance Problem
-----	--	---

CIRCUIT DESCRIPTION

Refer to DTC P0120 on page DI-44.

HINT:

This is the procedure of throttle position sensor.

DTC No.	DTC Detection Condition	Trouble Area
P0121	While vehicle speed drops from 30 km/h (19 mph) or more to 0 km/h (0 mph), output value of throttle position sensor is out of applicable range (2 trip detection logic)	Throttle position sensor

INSPECTION PROCEDURE

HINT:

Read freeze frame data using the hand-held tester or the OBD II scan tool, as freeze frame data records the engine conditions when a malfunction is detected. When troubleshooting, it is useful for determining whether the vehicle was running or stopped, the engine was warmed up or not, the air-fuel ratio was lean or rich, etc. at the time of the malfunction.

1 Are there any other codes (besides DTC P0121) being output?

YES

Go to relevant DTC chart (See page DI-16).

NO

Replace throttle position sensor.

2003 TOYOTA TACOMA (RM1002U)

Author: Date:

310