CO/HC INSPECTION

EM02I-04

HINT:

This check is used only to determine whether or not the idle CO/HC complies with regulations.


1. INITIAL CONDITIONS

- (a) Engine at normal operating temperature
- (b) Air cleaner installed
- (c) All pipes and hoses of air induction system connected
- (d) All accessories switched OFF
- (e) All vacuum lines properly connected

HINT:

All vacuum hoses for EGR systems, etc. should be properly connected.

- (f) SFI system wiring connectors fully plugged
- (g) Ignition timing check correctly
- (h) Transmission in neutral position
- (i) Tachometer and CO/HC meter calibrated by hand
- 2. START ENGINE
- 3. RACE ENGINE AT 2,500 RPM FOR APPROX. 180 SE-CONDS



- 4. INSERT CO/HC METER TESTING PROBE AT LEAST 40 cm (1.3 ft) INTO TAILPIPE DURING IDLING
- 5. IMMEDIATELY CHECK CO/HC CONCENTRATION AT IDLE AND/OR 2,500 RPM

HINT:

When doing the 2 mode (idle and 2,500 rpm) test, these measurement order prescribed by the applicable local regulations.

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 1068

6. TROUBLESHOOTING

If the CO/HC concentration does not comply with regulations, troubleshoot according in the order given below.

- (1) Check heated oxygen sensor operation (See page DI–64).
- (2) See the table below for possible causes, then inspect and correct the applicable causes if necessary.

СО	НС	Symptoms	Causes	
Normal	High	Rough idle	1. Faulty ignition:	
			• Incorrect timing	
			• Fouled, shorted or improperly gapped plugs	
			Open or crossed high–tension cords	
			2. Incorrect valve clearance	
			3. Leaky EGR valve	
			4. Leaky exhaust valves	
			5. Leaky cylinder	
Low	High	Rough idle	1. Vacuum leak:	
		(Fluctuating HC reading)	Vacuum hose	
			Intake manifold	
			Intake chamber	
			• PCV line	
			Throttle body	
High	High	Rough idle	1. Clogged air filter	
		(Black smoke from exhaust)	2. Plugged PCV valve	
			3. Faulty SFI system	
			• Faulty fuel pressure regulator	
			Clogged fuel return line	
			• Faulty MAF meter	
			Defective ECT sensor	
			Defective IAT sensor	
			Faulty engine control module (ECM)	
			• Faulty injector	

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 1069