
PR04Z-01

## **INSPECTION**

### NOTICE:

Be careful not to grip the propeller shaft tube too tightly in a vise as this will cause deformation.




# 1. INSPECT PROPELLER SHAFT AND INTERMEDIATE SHAFT FOR DAMAGE OR RUNOUT

- (a) Inspect the shafts for wear or damage.
- (b) Using a dial indicator, check the runout of the shafts.

  Maximum runout: 0.8 mm (0.031 in.)

If the shaft runout exceeds the maximum, replace the shaft.




#### 2. INSPECT SPIDER BEARING

- (a) Inspect the spider bearings for wear or damage.
- (b) Using a dial indicator, check the spider bearing axial play by turning the yoke while holding the shaft tightly.

Maximum bearing axial play: 0.05 mm (0.0020 in.)

If the spider bearing axial play exceeds the maximum, replace the spider bearing (See page PR-17).




### 3. 3-joint type:

# INSPECT CENTER SUPPORT BEARING FOR WEAR OR DAMAGE

Check that the bearing turns freely.

If the bearing is damaged, worn, or does not turn freely, replace it.



## 4. w/ Double cardan joint propeller shaft: INSPECT WITH DOUBLE CARDAN JOINT PROPEL-LER SHAFT

- (a) Inspect the shaft for wear or damage.
- (b) Inspect the double cardan joint for wear or damage.

If any problem is found, replace the propeller shaft assembly.

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 1841