TROUBLESHOOTING PROBLEM SYMPTOMS TABLE

SA090-10

Use the table below to help you find the cause of the problem. The numbers indicate the priority of the likely cause of the problem. Check each part in order. If necessary, replace these parts.

(w/ Differential locking system):

- Check that center differential lock mode is set.
- When switching differential Free ↔ Lock, the indicator lamp will blink if the gears of the differential lock sleeve are not meshed. If this occurs, when the tires are rotated to apply differential power to the differential, the differential locks and the indicator lamp lights up.

Symptom	Suspect Area	See page
	Vehicle (Overloaded)	_
	2. Spring (Weak)	SA-70
		SA-75
Bottoming		SA-208
	3. Shock absorber (Worn)	SA-72
		SA-78
		SA-205
	Tire (Worn or improperly inflated)	SA-118
	2. Stabilizer bar (Bent or broken)	SA-72
Sways/pitches		SA-122
	3. Shock absorber (Worn)	SA-72
		SA-78
		SA-203
	Tire (Worn or improperly inflated)	SA-4
	2. Wheel (Out of balance)	SA-4
	3. Shock absorber (Worn)	SA-72
		SA-78
	4. Wheel alignment (Incorrect)	SA-6
		SA-10
Front wheel shimmy	5. Ball joints (Worn)	SA-86
		SA-105
		SA-108
		SA-111
		SA-113
		SA-116
	6. Hub bearing (Loosen or worn)	SA-14
	7. Steering linkage (Loosen or worn)	-
	8. Steering gear (Out of adjustment or broken)	SR-54
		SR-73
	Tire (Improperly inflated)	SA-4
Abnormal tire wear	2. Wheel alignment (Incorrect)	SA-6
		SA-10
	3. Shock absorber (Worn)	SA-72
		SA-78
	4. Supposion porto (Morn)	SA-203
	4. Suspension parts (Worn)	
	Oil level (Low or wrong grade)	SA-41
Noise in front differential	2. Excessive backlash between pinion and ring gear	SA-45
	3. Ring, pinion or side gear (Worn or chipped)	SA-45
	4. Pinion shaft bearing (Worn)	SA-45
	5. Side bearing (Worn)	SA-45
	6. Differential bearing (Loosen or worn)	SA-45

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 1850

SUSPENSION AND AXLE - TROUBLESHOOTING

Oil leak from front differential	Oil level (Too high or wrong grade)	SA-41
	2. Front differential rear oil seal (Worn or damaged)	SA-45
	3. Side gear oil seal (Worn or damaged)	SA-45
	4. Companion flange (Loosen or damaged)	SA-45
	5. Side gear shaft (Damaged)	SA-45
Noise in rear axle	Oil level (Low or wrong grade)	SA-135
	2. Excessive backlash between pinion and ring gear	SA-141
		SA-158
		SA-176
	3. Ring, pinion or side gear (Worn or chipped)	SA-141
		SA-158
		SA-176
	4. Pinion shaft bearing (Worn)	SA-141
		SA-158
		SA-176
	5. Axle shaft bearing (Worn)	SA-126
	6. Differential bearing (Loosen or worn)	SA-141
		SA-158
		SA-176
0.11	Oil seal (Worn or damaged)	SA-126
Oil leak from rear axle	2. Rear axle housing (Cracked)	_
Oil leak from rear differential	Oil level (Too high or wrong grade)	SA-135
	2. Oil seal (Worn or damaged)	SA-135
	3. Companion flange (Loosen or damaged)	SA-141
		SA-158
		SA-176
Indicator lights do not light up	Fusible link (Blown)	_
	2. GAUGE fuse (Blown)	_
	3. Bulb (Burned out)	_
	4. Wiring or ground (Faulty)	_
	1. Diff. fuse (Blown)	_
Indicator lights do not light up	2. Diff. lock control switch (Faulty)	SA-199
(Diff. lock control switch RR or FR position)	3. Diff. lock ECU (Faulty)	SA-199
,	4. Wiring or ground (Faulty)	_
Differential lock does not operate	Diff. lock control switch (Faulty)	SA-199
	Diff. lock actuator (Faulty)	SA-199
	3. Diff. lock ECU (Faulty)	SA-199
	Differential carrier (Faulty)	_
		_
	5. Wiring or ground (Faulty)	
		BE-39
After differential lock, lock is not released When vehicle speed is higher than approx. 8 km/h (5 mph)	Speed sensor (Faulty) Diff. lock ECU (Faulty)	BE-39 SA-199

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 1851