## TROUBLESHOOTING PROBLEM SYMPTOMS TABLE

PR000-02

Use the table below to help you find the cause of the problem. The numbers indicate the priority of the likely cause of the problem. Check each part in order. If necessary, replace these parts.

Symptom	Suspect Area	See page
	1. Center bearing (Worn)	PR-5
		PR-13
Noise	2. Sleeve yoke spline (Worn)	_
	3. Spider bearing (Worn or Stuck)	PR-5
		PR-13
	Transmission extension housing rear bushing (Worn)	-
	2. Sleeve yoke spline (Stuck)	_
	3. Propeller shaft (Runout)	PR-5
		PR-13
	4. Propeller shaft (Imbalance)	_

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 1829