PP02C-01

PREPARATION - CHARGING (5VZ-FE)

EQUIPMENT

Battery specific gravity gauge	Battery
Belt tension gauge	
Torque wrench	
Vernier calipers	Rotor (Slip ring)