CHARGING (5VZ-FE) SST (Special Service Tools)

PP02A-0

(h)	09285–76010	Injection Pump Camshaft Bearing Cone Replacer	Rotor rear bearing cover
	09286–46011	Injection Pump Spline Shaft Puller	Rectifier end frame
	09820-00021	Alternator Rear Bearing Puller	
	09820-00031	Alternator Rear Bearing Replacer	
	09820–63011	Alternator Pulley Set Nut Wrench Set	
CERCONNIC CONTROL OF THE CONTROL OF	09950–60010	Replacer Set	Rotor front bearing
6	(09951–00500)	Replacer 50	

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 98