# **CONDENSER**

## **ON-VEHICLE INSPECTION**

AC085-01

### 1. INSPECT CONDENSER FINS FOR BLOCKAGE OR DAMAGE

If the fins are clogged, wash them with water and dry with compressed air.

#### NOTICE:

Be careful not to damage the fins.

If the fins are bent, straighten them with a screwdriver or pliers.

### 2. INSPECT CONDENSER AND FITTINGS FOR LEAKAGE

Using a gas leak detector, check for leakage of refrigerant. If there is leakage, check the tightening torque at the joints.

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 2540