
CRUISE CONTROL SYSTEM (w/o ETCS-i) HOW TO PROCEED WITH TROUBLESHOOTING

DI877_02

Troubleshooting in accordance with the procedure on the following pages.



2003 TOYOTA TACOMA (RM1002U)

Author: Date:

981